


Certificate of Compliance

4182 BH STUDY LOFT DRESSER SHELF

1. This product meets applicable U.S. consumer product safety requirements.  
1213 1303 1500 1513
2. Trendwood, Inc. (Sales@Trendwood.com)  
120 East Watkins Street  
Phoenix, AZ 85004  
(602) 416-7800
3. Manufactured by Trendwood, Inc.
4. Manufactured by Trendwood, Inc.
5. Trendwood, Inc. (Sales@Trendwood.com)  
120 East Watkins Street  
Phoenix, AZ 85004  
(602) 416-7800 contact: Scott Coor
6. Date: All products manufactured by Trendwood, Inc. Each carton is clearly labeled with the date - M/D/Y and place the product was manufactured.
7. Diversified Testing Laboratories 2013  
Specialized Technology Resources (HK) Ltd. 2013
8. Lab info: Diversified Testing Laboratories, Inc.  
Lab address - 336 West Front Street  
Burlington, NC 27215  
Phone - (336) 227-7710
9. STR Lab - Specialized Technology Resources (HK) Ltd.  
16-17/F Tower B, Regent Centre  
63 Wo Yi Hop Road, Kwai Chung, N.T., Hong Kong  
Tel: +(852) 2423 3092  
Fax: +(852) 2480 5436  
E-Mail: enquiries@strhk.com  
www.strhk.com





**DIVERSIFIED**  
**TESTING LABORATORIES, INC.**  
WORLDWIDE SERVICE

“We Test Per Your Request”

336 WEST FRONT STREET  
P.O. BOX 4004  
BURLINGTON, NORTH CAROLINA 27215  
PHONE (336) 227-7710 • FAX (336) 227-1175  
www.diversifiedtestinglabs.com

May 2, 2018

Mr. Nick Bullington  
TRENDWOOD, INC.  
120 East Watkins Street  
Phoenix, AZ 85004-2924

Dear Mr. Bullington:

One (1) **Seven Drawer, One Shelf Dresser Model: 4182-4319-4419-4810 with 8” Drawer Extension**, was tested on May 2, 2018 in Phoenix, AZ for compliance with ASTM F 2057-14, "Standard Safety Specification for Clothing Storage Units" (Tipover Test).

I certify that all tests were performed by me in accordance with the specification test requirements, and that the reported test results are true, valid and applicable to the unit tested. I further certify that **Seven Drawer, One Shelf Dresser Model: 4182-4319-4419-4810 with 8” Drawer Extension**, meets all minimum requirements of the above standard.

I tested the unit in the following sequence:

| <u>Section</u> | <u>Test Item</u>              | <u>Test Results</u> |
|----------------|-------------------------------|---------------------|
| 4.4 & 4.5      | Strength of Tipover Restraint | Meets Standard      |
| 4.6            | Attached Warning Label        | Meets Standard      |
| 7.1            | Stability of Unloaded Unit    | Meets Standard      |
| 7.2            | Stability with Load           | Meets Standard      |

If there are any questions or when we can be of further assistance, please let us know.

Sincerely,

Bobby E. Puett  
President

BEP/mr

